


20030303\*E4206001

FIG. 1





2025-05-20 15:00

FIG. 3

301		302		303		304		305		306	
Customer ID	Name	Postal Code		Address		Phone Number		Floor Plan			
00078723	Katsue Isono	123 -4567		Kadomatsu-cho 1-1, Kadomatsu-shi		06(6378) 5678		00078723m1 00078723m2			
00078724	Makio Isobe	234 -0056		Moriguchi-cho 2-22, Morita-shi		078(81) 1234		00078724m1			


APPROVED	CC	10
BY	CLASS	SUB
DRAFTSMAN		

203030 64406000

FIG. 4


201		301		203		204		401	
Appliance ID		Customer ID		Manufacturer Code		Model Code		Connection Point	
000001		00078723		0034		PQ01-83		1K01	
000002		03990212		0034		TV03-05		1L16	
000003		00078723		0034		PQ01-83		2L05	

FIG. 5




20090729.030607

FIG. 6



200905205001

FIG. 7



20090306 16:00


2023-06-06

FIG. 8

Operation Mode	Temperature Difference $\Delta T$	Preset Temperature Reaching Time $\Delta t$	Compressor Rotational Frequency
Cooling	2.3	6.0	2000
Cooling	5.0	10.7	2210
Cooling	3.2	6.8	2033
Cooling	3.3	6.9	2008
Heating	3.5	3.7	2039
Heating	5.5	5.0	2157
Heating	3.0	3.5	2001
Heating	2.0	3.0	1899
Heating	2.2	3.0	1948
Heating	3.6	3.7	2030
Heating	4.8	4.5	2074
Heating	2.5	2.9	1975




FIG. 9



1009079-030602

FIG. 10



10050779-030502

FIG. 11A




FIG. 11B

1201

1200

Failure Information	Customer: Katsue Isono
Address:	Kadomatsu-cho1-1, Kadomatsu-shi
Phone Number:	06-6378-5678
Location:	1F Kitchen(1K01)
Manufacturer Code:	034
Mode Code:	PQ01-83
Appliance ID:	000001
Abnormal Component:	Compressor
Abnormal Code:	PQX-822
Part Code:	PQP-07, PQS-15
Sketch:	1F, Ms. Isono's House

1202

1203

1204

1205

1206

1207

1208

1209

1210

1211